# WORK AUTHORIZATION

WA 005

(DOT) **VOLPE** 

AUTHORIZATION IS GIVEN TO INITIATE WORK AS DESCRIBED IN THE U.S. DEPARTMENT OF TRANSPORTATION (VOLPE CENTER)- TECHNICAL ASSISTANCE IAG #DW6995388401 AND AS AMENDED. THIS INFORMATION IS PROVIDED FOR COST TRACKING PURPOSES.

**SDMS Document ID** 

To Be Filled Out by the Remedial Project Manager:

Brief Description of Work to Be Done: SEE ATTACHED

Site Name: LIBBY ASBESTOS SUPERFUND SITE

EPA Site Id# 08BCRV00

Remedial Project Manager: Jim Christiansen

Period of Performance: From: June 15, 2003 To: September 15, 2003

Dollar Amount Needed: \$ 15,000.00

To Be Filled Out by the IAG Project Officer:

Previous Amount: \$ -0-

Total Amount to Date: \$ 15,000.00

DCN: LRV 015 03 T 8ALOE 50102D 08BCRV00 CO01

**IAG NUMBER** 

**OBJECT COST** 

SUPERFUND ACCOUNT ORG

**AMOUNT** 

Deob. Fm:

Oblig. To: DW6995388401

LRV 015 03 T 8ALOE 50102D 08BCRV00

CO01

\$15,000.00

JEFF MARSALA, CINCINNATI FINANCIAL MGMT. CTR.

COPIES TO:

ORIGINAL TO:

CAROL O'DONNELL, USEPA GRANTS SPECIALIST JOHN McGUIGGEN, VOLPE PROJECT MANAGER JHM CHRISTIANSEN, USEPA PROJECT OFFICER

AUDREY HENKEL, USEPA COST RECOVERY

JUDITH POWELL, PROJECT OFFICER

WAF 5 - Burlington Northern Oversight (BNSF Osight)

ATTACHMENT B
STATEMENT OF WORK -- WORK AUTHORIZATION FORM 5 (WAF 5)
(6/2/03) LIBBY ASBESTOS SITE

# Background:

As part of their support to the Libby Asbestos Project, the Volpe Center manages and conducts technical tasks related to Oversight of Cleanup/Remediation, including cleanup/remediation of asbestos-contaminated material (ACM) by Burlington Northern Santa Fe Corporation (BNSF) of its rail facilities and property.

#### Tasks to be Performed:

The Volpe Center shall provide the personnel, materials and supplies to conduct the following tasks:

Task 1. Review and Assess Plans and Specifications for Cleanup/Remediation. Perform engineering review and assessment of BNSF work plans and specifications for cleanup and remediation to include:

- a. Engineering and design documentation including analyses, results, drawings, specifications, and detailed schedules.
- b. Health and safety plans, including air sampling/monitoring
- c. Public information and coordination plans
- d. Site preparation plans
- e. Mobilization plans
- f. Contingency plans
- g. Removal area management
- h. Hazardous waste management
- i. Contaminated soil removal and containment
- j. Property restoration
- k. Inspection, resolution of discrepancies ("punch list"), and acceptance

Task 2. Work Plan. Review, validate, and coordinate the Work Plan for Cleanup/Remediation of BNSF facilities and property.

Task 3. Health and Safety Oversight. Perform on-site health and safety inspection. Conduct on-site observations of cleanup/remediation activities for compliance with the Comprehensive Health and Safety Plan (HASP) and Cleanup/Remediation work plans. Conduct sampling and analyses of soil and air to ensure health and safety during and after cleanup/remediation. Manage sampling and analysis data. Perform surveys to document sampling locations for future analysis of contamination patterns and exposure.

Task 4. Oversight of Cleanup/Remediation. Monitor planning and coordination functions required to prepare neighbors, cleanup/remediation staff, and oversight staff for

WAF 5 - Burlington Northern Oversight (BNSF Osight)

cleanup/remediation activities, and facilitate successful project completion. Includes monitoring and documenting all necessary notifications, meetings, agreements, and relocations. Includes documentation, validation, and reporting of plans, results, performance, and incidents.

## Cost Estimate

The estimated cost for conducting these tasks is provided on the coversheet for WAF 5.

# **Period of Performance**

The period of performance for conducting these tasks will be 90 calendar days from the date of agreement. The specific dates are provided on the coversheet for WAF 5.

### Concurrence:

EPA Region 8 and the Volpe Center have discussed this statement of work and mutually agree to its requirements, the estimated cost, and the schedule.

EPA Region 8 Remedial Program Manager

Volpe Center Project Manager: